

# **Nissan Pathfinder - Frozen Evaporator | HELLA**

**Nissan**

**Pathfinder (R51)**

**Model Year: 2007 – 2010**

**Frozen Evaporator**

**Reduced Air Outflow**

On the vehicles listed above, it is possible that the evaporator may freeze after long periods of driving, and the air outflow speed from the interior nozzles may be reduced.

A faulty evaporator temperature sensor is the possible cause. If the evaporator temperature sinks to around or even below 0°C, the evaporator freezes. The air flow is slowed.

Proceed as follows to rectify the problem:

- Read out the error memory
- Using the measured value blocks, carry out a target/actual comparison of the sensor measured values, or compare the interior temperature with the measured value of the sensor (evaporator must be cooled prior to this)
- If an error is entered and/or there are deviations, replace the sensor
- Clear the error memory if required
- Carry out a function test