

VW Tiguan - Light failure while driving | HELLA

VW

Tiguan

Model year: 01/2008-07/2011

Light failure while driving

The above vehicles may suddenly experience a partial or total failure of their lighting equipment while driving.

This problem may be caused by a defective fuse in the vehicle lighting circuit.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will replace the defective fuse with an improved one on the vehicles in question.