

# **Audi A1/A1 Sportback - Interrupted radio reception | HELLA**

**Audi**

**A1/A1 Sportback**

**Engine: 1.8 TFSI (DAJB)**

.

**Model year: (2015-2018)**

## **Interrupted radio reception**

With this kind of repair work, the customer complains that radio reception is interrupted when the rear-window heater is switched on.

The signal interference in this case is caused by damaged heater wires, i.e. damaged filaments in the rear window.

Repair notes:

In order to exclude other possible causes of malfunction, electrical and mechanical system tests (in accordance with vehicle manufacturer specifications) and also a fault code query using a suitable diagnostic unit should be carried out. If no other faults are found, the rear window has to be replaced.

**IMPORTANT:**

Please note that such repair work should only be carried out by an authorised specialist workshop and that the vehicle manufacturer's repair and maintenance instructions are to be observed!