

Fiat 500 X - Condensation in the footwell | HELLA

Fiat

500 X

Model year: up until 3/2017

With 9-speed automatic transmission (948TE)

Condensation in the footwell

It is possible that condensation occurs in the driver/passenger footwell of the above-mentioned vehicles.

The cause of this could be a loose drain hose for such condensation in the air-conditioning system.

The following steps can be taken to remedy the situation:

- Make the drain hose accessible
- Check the hose to ensure there is no blockage and that it fits properly
- Fix the hose to the evaporator housing with cable ties and check drainage for leaks