



Hyundai Tucson - bonnet warning lamp without function

Data sheet	
Manufacturer	Hyundai
Vehicle model	Tucson III
Engine	All models
Year of manufacture	2015 - 2020
Symptoms	Bonnet warning lamp defective

Important safety note

Bonnet warning lamp does not work

When the bonnet is open, a message appears on the instrument cluster as an illuminated warning lamp. On the vehicles mentioned above, this function may fail or the warning lamp remains off.

If other causes (e.g. bonnet lock contact) can be ruled out as the error, it is possible to remedy the situation by updating the software of the instrument cluster control unit. Contacting a Hyundai dealership is advisable.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.