



## Land Rover Range Rover IV - Water ingress in the area of the spare wheel well

Data sheet	
Manufacturer	Land Rover
Model	Range Rover IV (LG)
VIN	LG100000 - LG111073
Year of construction	2013
Symptoms	Moisture / water ingress in the area of the spare wheel well.

### Important safety note

## Land Rover / Range Rover IV (LG) - Water ingress in the area of the spare wheel well

In this repair case, the customer complains about moisture / a water leak in the area of the spare wheel recess.

Troubleshooting: A closer look at the spare wheel well revealed that the factory-fitted drain plug was only inadequately preventing water from entering from outside.

Remedy: replace the factory-fitted drain plug with a 1-way valve (OE No. AYB500080) in accordance with the vehicle manufacturer's instructions.

## **Note on hybrid vehicles**

### **IMPORTANT**

Please note that such work should only be carried out by an authorised specialist workshop and that the vehicle manufacturer's repair and maintenance instructions must be observed!

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.