

# Mercedes Benz - Engine power loss | HELLA

## Mercedes Benz

**Type: M-Class (W164) E-Class**

**(W211) S-Class (W221), GL (X164).**

**Engine: OM 629 (420 CDI)**

## Engine power loss

### Crankshaft sensor

On vehicles with OM 629 engines, the possibility exists that there is a loss of engine power. The reason for this may be an electrical interruption in the crankshaft sensor.

The vehicle manufacturer is already aware of the problem. As part of a service campaign, the vehicles will be checked and the crankshaft sensors will be replaced.

Nevertheless, one may assume that for various reasons not all vehicles have been checked and repaired.