

Mercedes Benz Vito 2 - Faulty function: Rear window wiper | HELLA

Mercedes Benz

Vito 2

Type: 639

Model year: from 2003

All models

Faulty function: Rear window wiper

Rear window washer system

Rear window defroster

If one or more of the above problems are identified on this vehicle model, this may be associated with corrosion of the multi-function relay.

One possible reason for this may water ingress in the left tail lamp. In this case, the relay installed under the lamp should be examined and replaced if necessary.

Then check the sealing surfaces of the tail lamp and enhance the seal if required.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.