



# NISSAN X-Trail - rough idling, reduced engine power, error codes: P1121 & P1122

Data sheet	
Manufacturer	NISSAN
Vehicle model	X-Trail
Engine	All models
Year of manufacture	2007 - 2014
Symptoms	Reduced engine power   Rough idling   Error codes: P1121, P1122

## Important safety note

## Rough idling and reduced engine power

The following problem is observed on the vehicles mentioned above. After starting the vehicle, there is rough idling, the engine speed goes up and down in short intervals and does not remain constant. Furthermore, the engine power is reduced and the following error codes may be stored in the control unit: P1121, P1122. A defective throttle valve housing can be diagnosed as the issue. Please proceed as follows to rectify the problem: Replace the defective throttle valve housing with a new one in accordance with the manufacturer's specifications and teach it in. Next, you should perform an error code query and a test drive to check whether the repair measure has worked.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.