

Opel Astra J - Turn signal failure check | HELLA

Opel

Astra J

Model year: 2011

Turn signal failure check

In the above vehicles, the turn signal failure check may be affected by a "software error".

The problem affects the software of the body control module - BCM. This may result in the driver information system not being able to detect or indicate a possible failure of the turn signals.

The vehicle manufacturer has already recognized the problem and taken corrective action as part of a service action by which the BCM software will be updated.

It is assumed that not all vehicles will have undergone the service action for various reasons.

Please note this information in the wake of complaints regarding the turn signal failure check.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.