



Seat Arona - vibrations from the front area during acceleration

Data sheet	
Manufacturer	Seat
Vehicle model	Arona
Engine	All models
Year of manufacture	2017 - 2021
Symptoms	Vibrations in the front area during acceleration

Important safety note

Vibrations in front areas during acceleration

The following problem is observed on the vehicles mentioned above. During the acceleration phase of the vehicle, vibrations and knocking noises may occur in the area of the drive axle (front).

It was possible to diagnose the cause as a defective drive shaft on the left side of the vehicle. Please proceed as follows to rectify the problem: Replace the defective drive shaft with a new one (item no. 2Q0 407 271 CA) according to the manufacturer's instructions.

Repeat the procedure on the right side if necessary. Finally a test drive should be performed to check the repair work.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.