



VW Golf VII - loss of coolant

Data sheet

Manufacturer

VW

Vehicle model

Golf VII

Engine

1.0i / 1.2i / 1.4i / 1.6i

Year of manufacture

2012 -

Symptoms

Loss of coolant

Important safety note

Loss of coolant

If a loss of coolant is detected in the vehicles mentioned above, the cooling system should be pressurised in accordance with the vehicle manufacturer's specifications and all components checked for damage/leakages. Paying particular attention to the coolant pump is advisable. Often the cause of coolant loss is a defective seal. To eliminate the problem, the seal and, if necessary, the entire coolant pump must be replaced. The cooling system must then be refilled and vented in accordance with the manufacturer's specifications. Ensure that the correct coolant additive is used and the correct mixing ratio is observed.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.