

VW Touareg - Engine warning light illuminates | HELLA

VW

Touareg 3.0i V6 (TDI)

Model: (7L_)/(7P5)

Model year: 2010

Engine warning light illuminates

The engine warning light illuminates on the vehicles mentioned above due to a defective exhaust gas differential pressure sensor.

A defective exhaust gas differential pressure sensor may become apparent if the engine no longer runs smoothly and/or if the engine warning light illuminates, for example.

If a defective sensor is not replaced, this may lead to consequential damage (including on the DPF, engine, etc.).

Repair note:

Replace differential pressure sensor.

- Exhaust gas differential pressure sensor

OE no. 059 906 051 A