

# **Toyota Auris - function restriction caused by seat adjustment | HELLA**

## **Toyota Auris**

**All models with mechanical handbrake operation**

**Production: Great Britain, Turkey**

**Year of construction: up until 2007**

## **Function restriction caused by seat adjustment**

If the driver's seat is moved to the forward-most position right up to the end stop on the above-mentioned vehicle model, this can lead to limited function of the handbrake lever.

## **Cause**

One possible cause of this may be too long actuation travel or incorrect basic setting of the handbrake mechanism.

## **Remedy**

We recommend the following basic setting:

the handbrake's lever travel should be set so that the locking limit is reached between 3-7 detents.

Please always observe here the relevant maintenance and repair instructions provided by the vehicle manufacturer!