Citroen Dispatch / Jumpy - Illumination of the engine control light and sporadic problems on engine start | HELLA

Citroen

Dispatch / Jumpy

Models I/II from 20 March 2006

Illumination of the engine control light and sporadic problems on engine start.

On the above mentioned vehicles sporadic problems may occur on engine start or the engine may die. In addition the engine control light may illuminate. This problem may be caused by a damaged wiring harness above the power steering pump (see figure). The fault on the wiring harness may be caused by "chaffing" on the cable harness guide. To rectify this problem, the wiring harness should be checked. Repair / renew damaged areas and fasten correctly (incl. protector).



(i) Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.