



Fiat 500 / 500C - error code P0325 / P0135 and engine control lamp comes on

Data sheet	
Manufacturer	Fiat
Vehicle model	500 / 500C
Engine	0.9i/1.2i
Engine code	312A6.000/169A4.000
Year of manufacture	2007 - 2016
Symptoms	Error code P0325/P0135 Misfiring Engine control lamp lights up

Important safety note

Software flaw in the engine control unit

In the case of the above-mentioned vehicles with manual transmission, a software flaw in the engine control unit can cause the engine control lamp to suddenly light up while the car is being driven and the error code P0135/P0325 to be stored in the control unit. In some cases, the engine also misfires.

The error can be corrected by means of a software update. Prior to such updating, electrical and mechanical sources of error should first be excluded.

Furthermore, it is advisable to contact a Fiat workshop.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the

document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.