



Fiat 500 X - unable to remove ignition key or ESP light comes on

Data sheet	
Manufacturer	Fiat
Vehicle model	500 X
Year of manufacture	2014 - 12.2016
Symptoms	Unable to remove ignition key and/or ESP lamp lights up and/or the electric parking brake does disengage

Important safety note

Faulty ESP/ABS control unit software may lead to various symptoms in the Fiat 500 X

The following symptoms may occur in the above-mentioned vehicles due to faulty ESP/ABS control unit software:

- Unable to remove ignition key
- ESP lamp lights up when cornering
- Electric parking brake does not disengage with active "Auto-Hold" function

In an effort to rule out other causes, check all possible system components and read out/delete the fault memory.

If no errors are identified, update the ESP/ABS software. For this purpose, it is advisable to contact a Fiat workshop

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.