

Opel Zafira B - Steering angle sensor cannot be calibrated | HELLA

Opel

Zafira B , CDTI

Engine: Z19 DTH

Model year: from 2005

Steering angle sensor cannot be calibrated.

If the steering angle sensor cannot be calibrated with the diagnostics device in the above vehicle, the following procedure may be successful.

- Disconnect the battery.
- Wait for 5minutes.
- Remove the steering wheel.
- Align the steering angle sensor (centre position).
- Install the steering wheel.
- Connect the battery.

Then the calibrate using the diagnostics device.

Follow also the installation and removal instructions and the safety regulations when handling airbag systems of the vehicle manufacturer.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.