



Volkswagen Transporter T6 - noise when outside temperatures low

| | |
|---------------------|--|
| Data sheet | |
| Manufacturer | Volkswagen |
| Vehicle model | Transporter T6 |
| Engine | 2.0-litre diesel |
| Engine code | CXEB/CXFA/CXHA/CXGA/CXGB/CXGC/ CXHB |
| Year of manufacture | 2015 - 2017 |
| Symptoms | Noise when outside temperatures low |

Important safety note

Noise when engine is cold and outside temperature is low

With the above-mentioned vehicles, rattling, rather non-specific noises may occur when the engine is cold and the outside temperature is low. The noise disappears when operating temperature returns to normal. The dual-mass flywheel could be a possible cause of the problem.

In order to rule out other causes, the engine and transmission suspension and also other components (which could trigger the noise) should be inspected and checked. In addition, the error memory of the engine control unit is to be read out. If no error is detected, a software update of the engine control unit should be carried out. The modified characteristic values can help to ensure that the noises no longer occur.

It is always advisable to contact a VW workshop when remedying such problems.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.