



Ford Mondeo modellyear '96 Central locking with Double locking

If the complaint is a non operational system it could be due to a deteriorated soldering point.

The deteriorated soldering point is located on the right hand side of the vehicle under the carpet of the front seat. For the repair consider the following steps:

1. Remove right hand side panel.
2. Lift up carpet in front of the right seat carefully.
3. Remove adhesive tape from wiring harness.
4. Search out the cables which are connected to the soldering point.
5. Examine the soldering point and cables for faulty insulation (if all cables and the soldering point are o.k. the fault cause lies elsewhere).
6. Replace all faulty cables complete with the soldering point.
7. Install the new cables with soldering connectors into the wiring harness.
8. Insulate the wiring harness with insulation tape.
9. Refit parts in reverse order.