



## ***Kia Sportage Model year 2005***

### **Cold-starting problem**

In the case of some Sportage models from model year 2005, cold-starting problems can occur at freezing temperatures, or cold starting may no longer be possible.

In some cases, the exhaust system can ice up so much due to temperature and condensed water that it is sometimes no longer possible to start the engine.

Only conversion of the exhaust system using modified parts with different diameter and angle can solve the problem. In relation to this, the main and middle silencers must be replaced:

