



Mercedes Benz Type W 210 with engines 602.982, 604.91, 606.9, 611.9
Mercedes Benz Type W 202 with engines 604.91, 611.96
Mercedes Benz Type W 140 with engine 606.9

Fault code **P-1482 (glow plug power control unit faulty) in the fault memory**

If the above-mentioned fault code is stored in the fault memory, the cause could be the cable connection between the glow plug power control unit and the engine control unit.

For this reason, the cable (signal, earth, and supply voltage) should be checked for a possible loose contact, breaks, a short to earth, or a short circuit to the positive connection. If the cable connection is OK, the glow plug power control unit should be checked and, if necessary, replaced.