



## **Mini (R50, R53)** **Mini One, Mini Cooper, Mini Cooper S**

### **Noise through ABS/ASC/DSC**

In the case of the above-mentioned vehicles, a noise can occur that is perceived only for a very short time after the engine has been started and a speed of around 15 km/h has been reached. This appears to come from the area behind the instrument panel trim. The noise occurs again only when the engine has been restarted and the above-mentioned speed has been reached. The noise occurs when the ABS/ASC/DSC unit carries out its self-test. The intensity of the noise can vary depending on the vehicle. Care must be taken that the brake lines (in particular in the area of the wiper motor) do not touch the bodywork, since this can lead to increased noise.