



## **Peugeot 206** **With 1.4-litre and 1.6-litre petrol engine** **or 1.9-litre and 2.0-litre diesel engine**

### **Build-up of smoke in the instrument cluster, failure of electrical components, short-circuits.**

If there are complaints with these vehicles about the above-mentioned faults, one possible cause is a damaged earth cable in the engine bay.

The cable affected is the earth cable between the battery and the transmission. In relation to this, the cable lug on the transmission breaks. In order to eliminate the fault, the earth cable must be repaired and must be laid in such a way that it is free of tension, so that repeat damage is prevented. Failed components, or components which have been damaged due to short-circuits, must be replaced.