



Bulletin

Land Rover Range Rover Sport V6 Model year: 2012 Vehicle Identification Number: LW000016 to -323768

Contact between the DRS cable and the positive battery cable

There may be contact between the DRS (dynamic response system) cable and the positive battery cable in the above vehicle.

The constant contact between the two cables may cause damage to the cable insulation.

The DRS cable may heat up when in contact with the positive battery cable, which can cause damage to the electronic components.

The vehicle manufacturer has already addressed the issue.

The cables are inspected for abrasion in the specialist workshop, and are replaced if necessary.

An additional clip is installed in the affected vehicles to ensure sufficient distance between the cables.