



Renault Laguna II With 2.2l diesel engine

Loss of performance and rattling noises from the engine bay.

If there are complaints with these vehicles that the engine no longer has full performance and that rattling noises can be heard from the engine bay, one possible cause is a defective flap module. This is located between the intake pipe and the cylinder head. In the case of the above-mentioned faults, it is possible that the control shaft is broken in the flap module, and that a flap is no longer opening and closing.

In order to eliminate the fault, the flap module must be replaced.



Flap module



Flap module (removed)