



Renault Twingo up to model year 1999

Charging control lamp lights up faintly

With the above-mentioned vehicles with a two-line instrument display (see photo) the charging warning lamp may light up faintly when the vehicle is idling. In this case the charging circuit must be checked. If this is OK, the instrument display panel must be replaced with a modified unit. To do this proceed as follows:

- Disconnect the battery
- Remove 2 screws for the display unit, behind the steering wheel, on the dashboard
- Remove the display unit from the dashboard
- Disconnect the plug
- Check the condition of the plug

Install the new instrument display panel in the reverse order to removal. Enter the radio code again if necessary and set the correct time on the clock.

