



VW Golf 4 + Passat 3B

Failure of speedo- and odometer

On the above-mentioned vehicles a software failure can cause the distance and speed not to be displayed on the instrument cluster. The following Bosch instrument clusters can be affected by this:

Golf: Instrument clusters with tachometer
Version number V14 up to V20

Golf: Instrument cluster with multifunction display
Version number V14 up to V19

Passat: Instrument cluster with version
number up to V13

Because the speed sensor isn't the cause of the problem, the fault can only be rectified by replacing the instrument cluster.

