



Audi A6

Model series 4B2, 4B4, 4B5, 4B6

Model year 1997 - 2005

The ESP warning light comes on.

If there are complaints with these vehicles that the ESP warning light comes on and the fault entry "Fault memory engine control unit" or "Load / speed signal from the engine control unit" is stored in the fault memory, one possible cause is a fault in the engine management. Since the ESP usually also intervenes in the engine management to limit torque, for example, a system fault must not occur. If there is a fault, this can lead to the above-mentioned fault in the ESP system and to the ESP switching off. To eliminate the fault, take a readout of the fault memory of the engine control unit and eliminate any faults found. Then delete the fault memory of the ESP control unit.