



## **BMW E34 520i 24V + 525i 24V (M50 engine)**

### **Defective oxygen sensor cable**

If it is routed too tightly, the oxygen sensor cable in the above-mentioned vehicles can wear through or break. When the sensor is replaced, the cable should be routed between the cable clip and the sensor with a 360° loop as strain relief.

You can find suitable replacement sensors (photo) in the Hella oxygen sensor range.

