



BMW

E46

Engine: 2.0 i (206S4)

Model year: 11.98–02.00

Rough idling, engine runs in limp-home mode

If, in the case of the above-mentioned vehicles, complaints such as rough idling, lean mixture, fault code lambda probe or engine runs in limp-home mode arise, the cause may be a corroded line for the crankcase breather.

The engine may draw additional air via a defective breather.

To resolve the problem, a modified breather line should be installed and the fault memory deleted.