



Ford Galaxy from model year 2001 With 2.0-litre / 2.3-litre petrol engine

Poor performance in the middle engine-speed range.

If there are complaints with these vehicles about poor performance and failure to reach top speed, one possible cause is a software problem in the engine control unit. In this case, the fault may be due to incorrect calibration of the octane-rating adjustment. In order to eliminate the fault, new, updated software must be installed in the engine control unit. Vehicles from model year June 2002 were shipped with updated software from the factory.

Bulletin

