



FORD

Ka, model years 1996-2008

Engine: 1.3L and 1.6L Duratec-8V

Streetka, model years starting 2003

Engine: 1.6L Duratec-8V

Fiesta, model years 2001-2008

Engine: 1.3L Duratec-8V

Motor control light is lit

**Error code: P0030, P0031, P0032, P0053,
P0130, P0131, P0132, P0133, P0134**

Problem:

One or more error codes are displayed.

Possible cause:

Overheating of the heated lambda probe.

Solution of the problem:

Check the lambda probe and if necessary replace with a new, revised lambda probe. Then the engine control unit must be programmed with a new calibration.

If no programming is done, this can lead to collapse of the lambda probe or to damage to the running of the engine. The control unit software can be updated only by an authorised dealer.