



BULLETIN

Jeep **Grand Cherokee (WH/W2), Commander (XH)** **Model year: 2007 - 2008** **Chrysler** **300 (LE / LX / L2)**

Fault on the electronic ignition lock module

In the vehicles listed above, the electronic ignition lock module WIN (Wireless Ignition Node) may get caught between the "START" and "RUN" positions.

The ignition switch may jump back to the "OFF" or "ACCESSORY" position.

This may lead to malfunctions and failure of certain electrical functions:

- Reduced engine power
- Reduction or failure of the support of the brake booster and power steering
- Deactivation of vehicle safety functions (e.g. front air bags)

The risk of accident is increased through the failure of certain electrical functions.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

The WIN module (Wireless Ignition Node) and remote control for opening and closing the vehicles are checked and exchanged if necessary.