



Lexus LS 400 (UCF20) Model year: 1994–2001

VSC lamp lights up / VSC without function

With the above-mentioned vehicles, the control light for the electronic stability program (VSC OFF, fig. 1) can be permanently lit after the battery has been replaced. In addition, the VSC/ESP cannot be activated by pressing the switch (fig. 2). The VSC/ESP is not activated by driving routine either.

To remedy the situation, the ground connection should be disconnected from the battery again for a few minutes and then re-connected. In many cases, the VSC/ESP control light goes out again after this and deactivation/activation via the switch is possible again.



Fig. 1



Fig. 2