



## **Mercedes Benz ML 270 CDI Model year: 11.1999 - 06.2005 Engine: OM 612,963**

**Engine control light is on  
Vehicle in emergency running mode  
Error code: P1189 "intake duct  
shutdown"  
Engine power loss**

If one or more of the above problems are identified on this vehicle model, this may be associated with a broken linkage of the charge duct control. In this case, the linkage must be removed and replaced with a spare part modified by the vehicle manufacturer.

Spare parts:

Mounting clip: 611 098 01 26

Linkage: 611 098 02 26



Please follow the installation and removal instructions of the vehicle manufacturer.

**Bulletin**