Bulletin



© Hella KGaA Hueck & Co., Lippstadt 26.10.2007 1-1

Opel Vectra-C Model year from 2002 to 05.2003 All vehicles

ABS lamp lights up

If there are complaints from customers about the abovementioned fault, poor contacting could be the cause. As well as the above-mentioned fault, there could be complaints that the engine does not start or that the instrument displays in the cockpit are not correct (fluctuations in the displays). In this case, check the plug connection between the cable harness multiple plug and the ABS control unit. The faults listed can be caused by damage to this (bent, widened contact pins etc.). For this reason, the manufacturer supplies a repair set for maintenance.



