Bulletin



© Hella KGaA Hueck & Co., Lippstadt 23.02.2006 1-1

Porsche Cayenne S + Cayenne Turbo Model year : 01.10.2002 - 19.07.2003

Failure of electronic systems

In the above-mentioned vehicles, damage to the wiring system can lead to the failure of different electronic systems. A spring in the foot park-brake can sometimes come into contact with the wiring harness and damage this. In this case problems can occur with the following systems:

- Electric window winders
- Cockpit lighting
- Electric outside mirrors
- Interior lighting

If necessary, the wiring harness can be repaired professionally.

The vehicle manufacturer is taking and has taken service action to deal with the problem. Since it must be assumed, however, that not all vehicle owners have taken part in this action, the vehicle manufacturer should be contacted in the case of complaint.



