



Porsche Boxster | 911 (model 996) with engine managment DME | ME 7.2

Faulty idle speed and mixture adaptation.

If the engine management system loses voltage, due to a discharged or disconnected battery, it is possible that after re-connecting the battery the idle speed and mixture adaptation is faulty. To avoid this, consider the following after connecting the battery:

- Switch on the ignition for one minute, without moving the accelerator pedal.
- Switch off the ignition for at least ten seconds.

The throttle adjusting device is now parameterised.

The ECU of all DME engine management systems needs a few minutes, with engine running, to relearn the idle speed and mixture adaptation values.