## Bulletin



## Vauxhall Insignia Model year: 2010 - 2011

## Engine warning light comes on

## Error code: C1221, C1222, C1223, C1224

These mean that the input signal of the speed sensors is 0.

If the error codes can be linked with the above-mentioned problem, this could point to faulty control unit software.

According to the vehicle manufacturer, the situation can be remedied by programming the engine control unit with revised and improved software.

Such updating of software is only to be carried out by an authorised dealer.

© HELLA KGaA Hueck & Co., Lippstadt

Reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved. All rights reserved.

