



VW

New Beetle

Model year: 05.2005 to 10.2005

Engine does not start / Immobilizer activated / Faulty instrument cluster

With the above-mentioned vehicles, a faulty condenser in the instrument cluster can lead to the immobilizer "blocking" at low temperatures. The vehicle can then no longer be started up.

The vehicle manufacturer initiated a service campaign to deal with the problem described, where vehicle owners were contacted directly by the vehicle manufacturer. The instrument clusters of those who reacted were checked and replaced if appropriate. It must be assumed, however, that there are still vehicles driving around that were not brought in to the garage for servicing for one reason or another. Please take this into account when considering complaints connected with vehicle start-up.

Bulletin

