



VW **Polo (Type 6N2)**

CD-player lighting flickers.

If there are complaints with these vehicles that the CD-player lighting starts to flicker in the case of some instrument-lighting settings, one possible cause is a software fault in the CD player. If the fault occurs, and only the CD-player lighting is affected, a fault in the setting of the instrument lighting can almost be excluded. In order to eliminate the fault, the CD player must be replaced.