



*Opel Corsa-B, build year up to 1993*  
*Tigra, build year up to 1995*  
*Astra-F, build year up to 1992*  
*Vectra-B, build year up to 1996*  
*Calibra, build year up to 1990*  
*Omega-B, build year up to 1994*

Turn signal lever does not return to neutral position automatically.

If the turn signal lever does not return to the neutral position after indicating, although the turn signal lever is okay, the cause can be due to the following:

The turn signal lever is incorrectly, or only on one side, mounted to the steering column.

To rectify the problem remove the steering column cover and engage the turn signal lever correctly. In this case a new turn signal lever is not necessary.

