



## ***Audi A4*** ***Model year from 2001*** ***All models with headlight cleaning*** ***system***

### **Failure of the headlight cleaning system.**

If there are complaints with these vehicles that the headlight cleaning system fails, one possible cause is a lack of voltage supply. If the fuse is undersized for the headlight cleaning system, it will blow. To eliminate the problem, the faulty fuse has to be replaced by a one with a higher capacity (30 A). This problem affects fuse no. 37 in the fuse box on the left-hand side of the dashboard.

#### **Note:**

Make a note of the fuse replacement and the capacity of the new fuse in the operating instructions and the cover of the fuse box.