



Mercedes Benz V-Class (Type 638) All models

Water ingress on the combination rearlights.

If there are complaints with these vehicles about water ingress in the rear area of the vehicle, one possible cause is a trapped cable loom on the combination rearlights.

In order to eliminate the fault, the combination rearlight affected must be removed and the cable loom laid correctly.

In order to ensure that the combination rearlight seals perfectly, a new seal should be inserted before installation.

Bulletin

