



## ***Renault Clio 2, 1, 5D dCi Engine: K9K 704 Model year: 2001 - 2006***

### **Low beam not functioning Defective relay contact**

If the low beam has failed in the above-mentioned vehicles, this may be associated with defective positioning of the low beam relay in the plug base. Since the relay is mounted in the footwell below the glove compartment on the front passenger's side, the defect may have been caused by front passenger "foot contact." In this case, the position, fastening and plug of the relay must be checked and repaired if necessary. We also recommend securing the relay on the relay socket with a cable tie.