

# Citroen C4 - Grinding noises coming from rear axle | HELLA

**Citroen**

**C4**

**All models up to model year 10/2006**

**Hand-brake cables jam**

**Grinding noises coming from rear axle**

If the problems mentioned above are detected, this may be due to a hand-brake cable becoming stiff or stuck.

Corrosion or internal damage can then cause the hand-brake cable to jam. If this happens, the lever on the brake caliper will not be able to move into its end position, which in turn causes the brake pad to press lightly against the brake disc. The resulting friction during driving generates unpleasant noises, and also causes the brake pad and brake disc to wear.

This defect often occurs in cold weather conditions.

## **Repair note**

It is not possible to repair the defective components. If damaged, both handbrake cables need to be replaced. If the brake pads or the brake discs have also been damaged in the process, renewal of these components is also recommended.

### **Important safety note**

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.