



Fiat Punto 199: coolant loss

Data sheet

Manufacturer

Fiat

Vehicle model

Punto 199

Engine


1.2i/1.4i 8-valve engine

Model year

2012 - 2019

Symptom

Coolant loss


 **Important safety note**

Fiat Punto losing coolant

If the above-mentioned vehicles are losing coolant, focus particularly on the upper coolant hose on the radiator.

If you identify a leak here, replace the hose with a modified version (55703225).

After having completed the repair refill the cooling system, bleed the cooling system and check for leaks according to the manufacturer's instructions.



Cooling water hose on the radiator

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.