

Ford Transit Connect - Poor wiper performance | HELLA

Ford

Transit Connect

Model year: 2011-6-1 - 2011-10-31

Poor wiper performance

Loose wiper arms

Wiper function failure

On the vehicles listed above, there may be instances where the wiper arms become loose from the wiper arm holders. This is usually caused by a loosened hinge pin that connects the wiper arm to the holder. A poor wiping pattern, due to low contact force, may be indicative of loose wiper arms.

The vehicle manufacturer has already addressed the problem and notified the owners of the affected vehicles. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or repaired.

To correct this, the existing wiper arms should be exchanged for modified wiper arms.