

# **Renault Trafic - MIL (malfunction indicator lamp / engine warning light) comes on during longer downhill journeys | HELLA**

**Renault**

**Trafic**

**Model Year: 2011 – 2013**

**Engine: M9R-630**

**MIL (malfunction indicator lamp / engine warning light) comes on during longer downhill journeys**

**Fault codes: P0201 - P0204**

**Electric circuit, injection valve, cylinders 1 - 4**

If the fault described above occurs together with the listed error codes, a possible cause may be defective software in the engine control unit.

As a result of faulty calibration of the engine control unit, the above-mentioned error codes can be triggered too soon.

Remedy:

First of all, read out the error memory and delete the fault codes. Recalibrate the engine control unit with the improved software (237613537R).

Finally a test drive should be carried out and the error memory read once again.

In such cases, please contact an authorized workshop.